

Detailed Facility Report

Facility Summary

DIFAZIO INDUSTRIES 38 KINSEY PLACE, STATEN ISLAND (SUBDIVISION), NY 10303

FRS (Facility Registry Service) ID: 110070626653

EPA Region: 02 Latitude: 40.628641 Longitude: -74.170122 Locational Data Source: FRS

Industry: Carwashes Indian Country: N

Enforcement and Compliance Summary

Statute	CWA
Insp (5 Years)	-
Date of Last Inspection	-
Current Compliance Status	No Violation Identified
Qtrs with NC (of 12)	0
Qtrs with Significant Violation	0
Informal Enforcement Actions (5 years)	-
Formal Enforcement Actions (5 years)	-
Penalties from Formal Enforcement Actions (5 years)	-
EPA Cases (5 years)	-
Penalties from EPA Cases (5 years)	-

Regulatory Information

Clean Air Act (CAA): No Information

Clean Water Act (CWA): Minor, Permit Effective (NYR00G324) Resource Conservation and Recovery Act (RCRA): No Information

Safe Drinking Water Act (SDWA): No Information

Other Regulatory Reports

Air Emissions Inventory (EIS): No Information

Greenhouse Gas Emissions (eGGRT): No Information

Toxic Releases (TRI): No Information

Compliance and Emissions Data Reporting Interface (CEDRI): No Information

Known Data Problems

Facility/System Characteristics

Facility/System Characteristics

System	Statute	Identifier	Universe	Status	Areas	Permit Expiration Date	Indian Country	Latitude	Longitude
FRS		110070626653					N	40.628641	-74.170122
ICIS-NPDES	CWA	NYR00G324	Minor: General Permit Covered Facility	Effective	Storm Water Industrial	10/01/2024	N	40.6288	-74.17051

Facility Address

	System	Statute	Identifier	Facility Name	Facility Address
	FRS		110070626653	DIFAZIO INDUSTRIES	38 KINSEY PLACE, STATEN ISLAND (SUBDIVISION), NY 10303
ſ	ICIS-NPDES	CWA	NYR00G324	DIFAZIO INDUSTRIES	38 KINSEY PLACE, STATEN ISLAND (SUBDIVISION), NY 10303

Facility SIC (Standard Industrial Classification) Codes

System	Identifier	SIC Code	SIC Description
ICIS-NPDES	NYR00G324	4225	General Warehousing And Storage
ICIS-NPDES	NYR00G324	6531	Real Estate Agents And Managers
ICIS-NPDES	NYR00G324	6719	Holding Companies
ICIS-NPDES	NYR00G324	7353	Heavy Construction Equipment Rental
ICIS-NPDES	NYR00G324	7359	Equipment Rental & Leasing
ICIS-NPDES	NYR00G324	7521	Automobile Parking
ICIS-NPDES	NYR00G324	7538	General Automotive Repair Shops
ICIS-NPDES	NYR00G324	7542	Carwashes

Facility NAICS (North American Industry Classification System) Codes

System	Identifier	NAICS Code	NAICS Description
		No data records returned	

Facility Tribe Information

Reservation Name	Tribe Name	EPA Tribal ID	Distance to Tribe (miles)
	No	data records returned	

Facility Industrial Effluent Guidelines

Effluent Guideline (40 CFR Part)	Effluent Guideline Description
No data records return	ned
	(

Enforcement and Compliance

Compliance Monitoring History (5 years)

Statute	Source ID	System	Activity Type	Compliance Monitoring Type	Lead Agency	Date	Finding (if applicable)
				No data records returned			

Entries in italics are not counted in EPA compliance monitoring strategies or annual results.

Compliance Summary Data

Statu	ute	Source ID	Current SNC (Significant Noncompliance)/HPV (High Priority Violation)	Current As Of	Qtrs with NC (Noncompliance) (of 12)	Data Last Refreshed
CW	/A	NYR00G324	No	09/30/2019	0	01/03/2020

Three-Year Compliance History by Quarter

Sta	atute Progr	Type	QTR 1	QTR 2	QTR 3	QTR 4	QTR 5	QTR 6	QTR 7	QTR 8	QTR 9	QTR 10	QTR 11	QTR 12	QTR 13+
	CWA (Sour	rce ID: NYR00G324)	10/01-12/31/16	01/01-03/31/17	04/01-06/30/17	07/01-09/30/17	10/01-12/31/17	01/01-03/31/18	04/01-06/30/18	07/01-09/30/18	10/01-12/31/18	01/01-03/31/19	04/01-06/30/19	07/01-09/30/19	10/01-01/03/20
	Fa	acility-Level Status	No Violation Identified	Undetermined											
		rterly Noncompliance Report History													

Informal Enforcement Actions (5 Years)

Statute	System	Source ID	Type of Action	Lead Agency	Date
			No data records returned		

Formal Enforcement Actions (5 Years)

No data records returned	

Environmental Conditions

Water Quality

Permit ID	Combined Sewer System?	Number of CSO (Combined Sewer Overflow) Outfalls	12-Digit WBD (Watershed Boundary Dataset) HUC (RAD (Reach Address Database))	WBD (Watershed Boundary Dataset) Subwatershed Name (RAD (Reach Address Database))	State Water Body Name (ICIS (Integrated Compliance Information System))	Impaired l Waters	Impaired Class	Causes of Impairment(s) by Group(s)	Watershed with ESA (Endangered Species Act)-listed Aquatic Species?
NYR00G324						No			Yes

Water Body Designated Uses

Rea	ach Code	Water Body Name	Exceptional Use	Recreational Use	Aquatic Life Use	Shellfish Use	Beach Closure Within Last Year	Beach Closure Within Last Two Years
			No	No	No	No	No	No

Air Quality

Nonattainment Area?	Pollutant(s)	Applicable Nonattainment Standard(s)		
Yes	Ozone	8-Hour Ozone (1997), 8-Hour Ozone (2008), 8-Hour Ozone (2015)		
No Lead				
Yes Particulate Matter		PM-2.5 (1997), PM-2.5 (2006)		
Yes Carbon Monoxide		Carbon Monoxide (1971)		
No Nitrogen Dioxide				
No	Sulfur Dioxide			

Pollutants

Toxics Release Inventory History of Reported Chemicals Released in Pounds per Year at Site


TRI Facility ID Year Total Air Emissions Surface Water Discharges	Off-Site Transfers to POTWs (Publicly Owned Treatment Works)	Underground Injections	Releases to Land	Total On-site Releases	Total Off-site Transfers
	No data records returned				

Toxics Release Inventory Total Releases and Transfers in Pounds by Chemical and Year

Demographic Profile

EJSCREEN EJ Indexes

Eleven primary environmental justice (EJ) indexes of EJSCREEN, EPA's screening tool for EJ concerns. EPA uses these indexes to identify geographic areas that may warrant further consideration or analysis for potential EJ concerns. Note that use of these indexes does not designate an area as an "EJ community" or "EJ facility." EJSCREEN provides screening level indicators, not a determination of the existence or absence of EJ concerns. For more information, see the <u>EJSCREEN home page</u>.



Number of EJ Indexes Above 80th Percentile

5

View EJSCREEN Report

Demographic Profile of Surrounding Area (3 Miles)

This section provides demographic information regarding the community surrounding the facility. ECHO compliance data alone are not sufficient to determine whether violations at a particular facility had negative impacts on public health or the environment. Statistics are based upon the 2010 US Census and American Community Survey data, and are accurate to the extent that the facility latitude and longitude listed below are correct. The latitude and longitude are obtained from the EPA Locational Reference Table (LRT) when available.

Population Density	7,950/sq.mi.
Percent Minority	58%
Households in Area	63,866
Housing Units in Area	69,000
Households on Public Assistance	2,459
Persons Below Poverty Level	56,194
Geography	
Radius of Selected Area	3 mi.
Center Latitude	40.628641
Center Longitude	-74.170122
Land Area	85%
Water Area	15%
Income Breakdown - Households (%)	
Less than \$15,000	7,423 (11.77%)
\$15,000 - \$25,000	5,428 (8.61%)
\$25,000 - \$50,000	13,320 (21.13%)

Age Breakdown - Persons (%)				
Children 5 years and younger	13,688 (7%)			
Minors 17 years and younger	49,685 (26%)			
Adults 18 years and older	141,372 (74%)			
Seniors 65 years and older	20,387 (11%)			
Race Breakdown - Persons (%)				
White	113,946 (60%)			
African-American	31,801 (17%)			
Hispanic-Origin	66,320 (35%)			
Asian/Pacific Islander	13,848 (7%)			
American Indian	1,158 (1%)			
Other/Multiracial	30,305 (16%)			
Education Level(Persons 25 & older) - Persons (%)				
Less than 9th Grade	9,434 (7.79%)			
9th through 12th Grade	11,675 (9.64%)			
High School Diploma	45,490 (37.54%)			
Some College/2-year	27,715 (22.87%)			
B.S./B.A. (Bachelor of Science/Bachelor of Arts) or More	26,852 (22.16%)			

Income Breakdown - Households (%)				
10,893 (17.28%)				
25,989 (41.22%)				